

NOTICE to MARINERS 003 of 2025

BUOY MOVEMENTS

Mariners are hereby advised:

that the following buoys have been re-located. The Latitudes and Longitudes for all are expressed as degrees, minutes and decimals.

Buoy No	Latitude	Longitude
23	53 deg 55.250965 mins N	003 deg 00.170438 mins W
24	53 deg 55.232630 mins N	003 deg 00.191910 mins W
25	53 deg 55.22636 mins N	003 deg 00.37863 mins W

Mariners are also advised that a new buoy (buoy No 27) has been added and is in the following location.

27 53 deg 55.19428 N 003 deg 00.43716 W

And has the following characteristics:

FI (2) G. 10 sec

ABP Fleetwood Tel 01253 879060 Richard Webb

Port Office Harbour Master

Fleetwood FY7 6PP 10.04.2025

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.