

PORT OF TROON

LOCAL NOTICE TO MARINERS

NO. 04 /2025

Mill Rock Buoy extinguished: TROON HARBOUR

BA CHART 1866

NOTICE IS HEREBY GIVEN that Mill Rock Port hand lateral mark is extinguished. Mariners are advised to navigate with extreme caution until a new top light is in place.

Continually improving
the operations and
services we provide

Working safely
and sustainably

Providing effective
infrastructure
and equipment

www.abports.co.uk

Byron O'Hanlon

Harbour Master/Pilot Ayr & Troon

02nd December 2025

Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are known to the masters or persons in charge of their vessel or craft.