

## **NOTICE TO MARINERS**

### **Lowestoft Approaches - Stanford Channel –**

#### **South Holm Buoy**

UTC ☒ BST ☐

This notice is to advise Mariners, Port Users and Vessel Operators that the South Holm lighted buoy, approx. position 52° 26.700'N, 001° 47.200'E, marking the southern extreme of the Holm Sand and southern entrance to the Stanford channel, is reported to be damaged which has effected the buoys top mark (as shown below).



Notice will be provided when the buoy has been repaired.

Please contact Lowestoft Port Control, VHF Ch14, Tel. 01502 572286, if additional clarification or information is required.

**Divisional Harbour Master East Anglia**

**14 February 2021**

**Notice to Mariners Currently in Force:**

**2006** No.5 **2007** No.13 **2009** No.19 **2011** No.7, No.10, No.19 **2012** No.3, **2013** No.17, No.19, **2015** No.24 **2016** No.12 **2017** No.5, No.22, No.24, No.32, No.34 **2018** No.34, **2019** No.2, No.18, No.27 **2020** No.1, No.5, No.17, No.24, No.26, No.29, No.40, No.43, No.44, No.45, No.47, No.50, **2021** No.01, No.8, No.9, No. 10