

PORT OF BARROW

NOTICE TO MARINERS No.12 of 2016

Hull penetrations

Mariners are advised that following the sinking and subsequent recovery of the fishing vessel Taliskar, initial investigations suggest that the cause of the incident was due to a hull penetration becoming corroded and subsequently failing. This consequently allowed water to enter the hull and cause it to sink.

Mariners are therefore advised that they check their own vessels or leisure craft to ensure such hull penetrations are in good order.

Port Office
Ramsden Dock Road
Barrow-in-Furness
Cumbria LA14 2TW

Tel: 01229 822911
Email: Barrow@abports.co.uk

Captain Guy Lockwood
Harbour Master

26th January 2016

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.