

## **NOTICE TO MARINERS**


### **LOWESTOFT APPROACHES – ‘TWIN’ BUOYS – SOUTH CARDINAL BUOY WITHOUT TOP MARK**

UTC  BST

Mariners and Port Users are advised that the South Cardinal Twin (or Sewer) Buoy, position 52°28.84’N, 001° 46.25’E, currently has no top mark.

The top mark has been damaged for some time, but has recently been removed. It is scheduled to be replaced ASAP.

The buoy remains lit and is otherwise marked correctly (see below photograph).



Mariners are requested to navigate with caution in the approaches to Lowestoft.

A notice will be promulgated to advise when the top mark is re-instated.

Please contact Lowestoft Port Control, VHF Ch14, Tel. 01502 572286 (Option 3), if further information is required.

**Divisional Harbour Master East Anglia**

**12 May 2022**

**Notice to Mariners Currently in Force:**

**2006** No.5 **2007** No.13 **2009** No.19 **2011** No.7, No.10 **2012** No.3, **2013** No.17, No.19, **2015** No.24 **2016** No.12 **2017** No.5, No.22, No.24, No.32 **2019** No.2, No.18 **2020** No.17, No.24, No.26, No.29, No.40, No.43, No.44, No.47, No.50, **2021** No.01, No.40, No.51, No.54, No.57, No.58, **2022** No.1, No.2, No. 13, No.18a, No.20, No.21, No.22, No.23

**Lowestoft | Wales & Short Sea Ports | Associated British Ports| Lowestoft | Station Square | Lowestoft | NR32 1BA | +44 (0) 1502 572286**