



PORT OF FLEETWOOD

NOTICE to MARINERS 007 of 2025

BUOY NO 16 UNLIT

Mariners are hereby advised:

No 16 buoy reported unlit.

Mariners are therefore requested to navigate with extreme caution in the Channel until such time as the buoy is relit.

ABP Fleetwood Tel 01253 879060

Port Office

Fleetwood FY7 6PP

Richard Webb

Harbour Master

12.09.2025

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.