



Associated British Ports - Lowestoft

**No 22
2020**

LOWESTOFT APPROACHES – EAST CARDINAL ‘SEWER’ BUOY
TOPMARK MISSING

Mariners and Port Users are advised that the topmark on the East Cardinal ‘Sewer’ buoy, position **52° 28.89’N, 001° 46.24’E**, is missing. Please take this into consideration when navigating in this area.

Notification will be provided once the topmark has been re-instated.

Please contact Lowestoft Port Control, VHF Ch14, or Tel. 01502 572286, if further information is required

Harbour Master

12th May 2020

Notices to Mariners Currently in Force: 2006 No.5 2007 No.13 2009 No.19 2011 No.7, No.10, No.19 2012 No.3, 2013 No.17, No.19, 2015 No.24 2016 No.12 2017 No.5, No.22, No.24, No.32, No.34 2018 No.34, 2019 No.2, No.18, No.27 2020 No.1, No.5, No.10, No.12a, No.17, No.20a, No.22