

## NOTICE TO MARINERS NO.32 of 2022

## Lightning Knoll Fairway Buoy Removed

**NOTICE IS HEREBY GIVEN** that Lightning Knoll lighted Buoy, Latitude 53°59.841'N, Longitude 003°14.280'W has been permanently discontinued.

Mariners are advised to keep a good lookout and make use of the leading lights and other aids to navigation.

Marine Control Ramsey Way Barrow-in-Furness Cumbria LA14 2TB Tel: 01229 822911 Email: barrowmc@abports.co.uk R Rhodes Pilot

26.09.2022

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the Masters or persons in charge of their vessels or craft.