

***ABP* ASSOCIATED BRITISH PORTS FLEETWOOD**

NOTICE to MARINERS 21 of 2015

Obstruction

Mariners are hereby advised that an obstruction has been observed in a position approximately one cable south west of the No.7 buoy.

It is described as a tripod structure, protruding perhaps a couple of metres above the seabed.

Mariners are advised to avoid this area until the obstruction can be marked or removed.

LNtM 10/2015 is hereby cancelled

Captain Guy Lockwood
Harbour Master
25th November 2015

Owners, agents, charterers, fishermen and recreational sailing organisations should ensure that the contents of this notice are made known to the Masters or persons in charge of their vessels or craft.