

Port of Garston

NOTICE TO MARINERS No 004 of 2018 REPAIRS TO EAST OUTER WALL AT STALBRIDGE LOCK APPROACH

Further to NTM No 003 changes to the repairs are now in progress.

The works are still being carried out in the same location.

The new equipment will be deployed from the quay edge to the wall base and protrude no further than 2 metres from the quay wall.

A listening watch on VHF Channel 20 will be maintained throughout the works.

Mariners are advised to contact "Stalbridge Lock" on VHF Channel 20 before entering the Garston Channel.

A further Notice to Mariners will be issued on completion of the works.

C. Coulbeck

Assistant Dock Master, Garston