



PORT OF SILLOTH NOTICE TO MARINERS NO. 04/2015 *(revised 11/09/15)*

LOCAL PORT SERVICE (LPS)

CHANGE TO INBOUND VHF REPORTING PROCEDURE

NOTICE IS HEREBY GIVEN THAT, vessels are instructed to make contact with 'Silloth Harbour Radio' (VHF CH12) as detailed below.

For Inbound passages VHF contact should be made approximately 2 hours prior to high water Silloth, before the vessel passes Maryport, **at position 54° 42.2'N 003° 34.0'W**.

The following information must be provided to the LPS:

- Number of persons on board (including pilot).
- Draft.
- Any defects.
- Request for supply of fresh water.

An additional VHF report should be made to 'Silloth Harbour Radio' when 1.0nm from the 'Solway Buoy'.

For Outbound passages VHF contact must be made prior to letting go. The following information must be provided:

- Number of persons on board (including pilot).
- Draft.
- Any defects.
- Destination.

A final VHF report should then be made to 'Silloth Harbour Radio' on clearing the 'Solway Buoy'.

Capt E.H.Deeley - Harbour Master - Silloth Docks

2nd September 2015

www.abports.co.uk/Marine/Short_Sea_Ports/Silloth/

This notice supersedes 'General Notice to Master/Pilots 01/15 which is hereby cancelled.

Please see below for a full list of in force NtM's.

Current 'In Force' Notices to Mariners:

04/2013 - Boarding and Landing of Pilots
03/2014 - Port of Silloth Breakwater - Wooden Dolphin/Lights
06/2014 - Port of Silloth Breakwater – Installation of Temporary F.G. Light
09/2014 - Navigation Buoys
10/2014 - Navigation Waypoints
01/2015 - Silloth Sewage Outfall Beacon – Light Extinguished
02/2015 - Maximum Draft Calculation
03/2015 - New Dock Entrance - Installation of Navigation Lights
04/2015 – Change to Inbound VHF reporting procedures